Part Number: SW90217
Description: OZSCR2x00 Controller Firmware
Release Number: 1.10
Release Date: 9/24/2019
Revision: A

New Features:

- N/A

Bug Fixes:

- Improved firing angle accuracy, especially at higher AC input frequencies

Compatibility Notes:

- This version of the OZSCR2x00 firmware must be used with Power Studio software SW90216 Rev 2.0 or newer
- This version of the OZSCR2x00 firmware must be used with a Power Studio configuration file CFG90217-0000 Rev 9.0.0 or newer
- This version of the OZSCR2x00 firmware must be used with OZSCR2x00 embedded bootloader SW90190-0502 Rev 1.0 or newer
- This version of the OZSCR2x00 firmware requires an embedded FPGA image FW90206 Rev 2 or newer be installed on the OZSCR2x00 board