

Oztek Part Number: 908168
 USB to RS-485 converter



Connect Oztek Part Number 702938 (120 ohms, ¼ W resistor) across “TDA(-)” and “TDB(+)” terminals

Connect White with Blue stripe wire of 10891-XX to “RDB(+)” terminal




Connect Blue wire of 10891-XX to “RDA(-)” terminal



Connect Brown wire of 10891-XX to “GND” terminal



Connect Mod Bus. CAT 5 Cable to RJ-45 terminal to J20 connector of OZSCR **** board.




Oztek Part Number:10891-XX

Connect USB cable to computer



Final Assembly



Configure switches, as shown, to

- RS-485
- Echo OFF
- 2 wire
- 2 wire

Oztek Corp.	11 Continental Blvd, Unit B Merrimack, NH 03054
OZSCR RS-485/Mod Bus. Connections Quick Start Guide	
Drawing 10947 S. Walker	Revision B 1/4/2012