



# Software Release Notes

---

**Part Number:** SW90217  
**Description:** OZSCR2x00 Controller Firmware  
**Release Number:** 1.11  
**Release Date:** 11/13/2019  
**Revision:** A

## **New Features:**

- N/A

## **Bug Fixes:**

- Improved line voltage reading accuracy

## **Compatibility Notes:**

- This version of the OZSCR2x00 firmware must be used with Power Studio software SW90216 Rev 2.0 or newer
- This version of the OZSCR2x00 firmware must be used with a Power Studio configuration file CFG90217-0000 Rev 9.0.0 or newer
- This version of the OZSCR2x00 firmware must be used with OZSCR2x00 embedded bootloader SW90190-0502 Rev 1.0 or newer
- This version of the OZSCR2x00 firmware requires an embedded FPGA image FW90206 Rev 2 or newer be installed on the OZSCR2x00 board